


Sensor installation

simple and studied



Samples for typical installation places of **ACO** moisture sensors are at silo walls, at canted silo outlets, at material chutes, also inside a silo, with a sensor sleigh on or under a conveyor belt, in a screw conveyor, at continuous casting for bricks and tiles, as well as in mixers and before or behind dryers, and many more.

ACO presents a solution for nearly every possible installation situation, creating suitable solutions for your application.

For any installation of the **ACO** sensor only a 76 mm diameter hole is needed and three screw holes for 6 mm screw mounting.

